

Service Bulletin List

No.	Subject	Date
MSB-98E11-501	CORRECTION TO PISTON CLEARANCE	1999-05-15
MSB-98E11-502	CORRECTION OF TYPOGRAPHICAL ERRORS IN ENGINE 4M4 WORKSHOP MANUAL	1999-05-31
MSB-99E11-503	OMISSION OF INJECTION TIMING IDENTIFICATION MARK	1999-07-15
ESB-97E11-503	CORRECTING VALVE CLEARANCE & INJECTION TIMING INSPECTION & ADJUSTMENT PROCEDURE	1997-11-24
ESB-98E11-001	CHANGE IN CYLINDER HEAD BOLTS TIGHTENING DUE TO CYLINDER HEAD GASKET CHANGE	1998-12-15
MSB-97E11-001	CHANGE TIGHTENING TORQUE OF CRANKSHAFT BOLT	1998-12-15
MSB-99E11-505	ADDED DESCRIPTION OF TIMING CHAIN CLEARANCE MEASUREMENT	1999-11-15
MSB-99E11-001	CHANGE IN POSITIONS OF CRANKSHAFT IDENTIFICATION MARKS	1999-12-15
MSB-99E11-002	REVISION OF LASH ADJUSTER CLEANING PROCEDURE	1999-12-15